

ELECTED MEMBERS MOTIONS

APPENDICES

ITEMS:13.1

Ordinary Council Meeting

To Be Held

Wednesday, 22nd November 2023 Commencing at 5.00pm

At

Shire of Dardanup ADMINISTRATION CENTRE EATON 1 Council Drive – EATON

> This document is available in alternative formats such as: ~ Large Print ~ Electronic Format [disk or emailed] Upon request.



Tree Inspection and Recommendations Prepared for:

Department of Finance – Building Management & Works River Valley Primary School - Burekup 03/03/2021

Written by:

Ben Jorgensen ISA Certified Arborist AU-0334A



Summary

Scope of report

The scope of this report is to carry out a **Limited visual inspection** of the all trees at River Valley Primary School – Burekup that could potentially impact people or infrastructure in the event of a tree failure, individual trees were upgraded to a **Basic assessment** level where required. Trees were also assessed for maintenance requirements.

Assessment Synopsis

The aim of this assessment is to provide Building Management & Works with accurate information regarding the health and structural condition of the trees in question and make recommendations on suitable management options for risk mitigation and asset impact minimization.

This is done by visual inspection of the **crown**, root zone impact at ground level and visual inspection of the trunk to estimate the extent of wood decay. Root zone impact is assessed and estimated in reference to AS4970 – 2009 Protection of trees on development sites.

The use of the terms "Safe" or "Unsafe" when assessing trees is both imprecise and ambiguous as a tree cannot be free from defects or potential hazards, such a state is simply unattainable.

This assessment was carried out using the International Society of Arboriculture Tree Risk Assessment Method (TRAQ) which is a method of qualifying risk through estimating likelihood of tree failure, likelihood of impact and consequences of impact to potential targets within the tree impact zone. The assessment time frame for all inspected trees is 1 year. The Re-inspection interval recommendation for this site is 1 year and as soon as possible after each extreme weather event where tree damage is sustained.

Tree Inspection Explanatory Notes

Health - summarises observations of tree health made in the field:

Good - No significant pest or disease problems, expected growth rates, dense canopy, and good leaf colour.

Fair - Minor pest or disease problems, average growth rates, canopy perhaps sparse in places, or some chlorosis.

Poor - Serious pest or disease problems, poor growth rates, sparse canopy, or major leaf discolouration. Dead – The tree is dead.

Structure - summarises observations of tree structure made in the field:

Good - All forks sound, no major decay in limbs or trunk.

Fair - Some poor forks developing, or decay developing in limbs or trunk. Major failure unlikely.

Poor - Serious defects present, either poor forks, or decayed limbs or trunk; failure likely.

Individual tree inspections – The trees in this group have been identified as requiring specific methods of management and elevated risk levels.

Broad area inspections – The trees in the broad area groups have been identified as requiring generic methods of management.

Site Investigation

Individual Tree Inspections

Tree ID: 01. Species: Corymbia maculata (Western Spotted Gum) Location: K/PP Playground

Tree health: Good

Structure: Good

Comments: Tree has sustained 2 recent branch failures, these failures appear to be consistent with excessive loading during an extreme wind event- given the nature of the weather conditions that cause this type of branch failure, the likelihood of people being beneath the crown during this type of weather event is dramatically reduced – therefore the likelihood of impact is also dramatically reduced.

Risk assessment – Tree Part/Target: Deadwood overhanging playground

Likelihood of failure – Possible Likelihood of impact – Low Consequences of failure – Severe

Overall tree risk rating – Low

Recommendations: Carry out deadwood removal, minor load reduction pruning to over-extended laterals, carry out aerial inspection of crown during works – report to BMW if required



Kings Tree Care Arborist Report Mar 2021


Tree ID: 02. Species: Jacaranda mimosifolia (Jacaranda) Location: K/PP Playground

Tree health: Good Structure: Good Comments: Tree has branches impacting buildings

Risk assessment – Tree Part/Target: N/A Likelihood of failure – N/A Likelihood of impact – N/A Consequences of failure – N/A

Overall tree risk rating – Low

Recommendations: Carry out pruning for building clearances



Tree ID: 03. Species: Agonis flexuosa (WA Weeping Peppermint) Location: Northern fence line of K/PP

Tree health: Good Structure: Fair Comments: Tree has branches impacting building and carpark

Risk assessment – Tree Part/Target: N/A Likelihood of failure – N/A Likelihood of impact – N/A Consequences of impact – N/A

Overall tree risk rating – Low

Recommendations: Carry out crown lift pruning and building clearance



Tree ID: 04. Species: Corymbia maculata (Western Spotted Gum) Location: Eastern boundary overhanging K/PP building

Tree health: Good Structure: Fair Comments: Tree has deadwood throughout crown, over-extended branches and several stubs from branch failures

Risk assessment – Tree Part/Target: Deadwood and over-extended branches overhanging carpark and footpath Likelihood of failure – Probable Likelihood of impact – Low Consequences of impact – Severe

Overall tree risk rating – Low

Recommendations: Carry out deadwood removal, load reduction pruning to over-extended laterals and remedial pruning to damage



Kings Tree Care Arborist Report Mar 2021


Tree ID: 05.Species: Plantanus acerifolia (London Plane Tree)Location: Front entrance to school – Northern side

Tree health: Good Structure: Good Comments: Tree has branches impacting building

Risk assessment – Tree Part/Target: N/A Likelihood of failure – N/A Likelihood of impact – N/A Consequences of impact – N/A

Overall tree risk rating – Low

Recommendations: Carry out pruning for building clearance



Tree ID: 06. Species: Corymbia calophylla (Marri) Location: S/W corner of school

Tree health: Fair Structure: Fair Comments: Tree has deadwood throughout crown and over-extended lateral branches N/E side of crown

Risk assessment – Tree Part/Target: Deadwood and over-extended lateral branches overhanging play area Likelihood of failure – Probable Likelihood of impact – Low Consequences of impact – Severe

Overall tree risk rating – Low

Recommendations: Carry out deadwood removal and load reduction pruning to over-extended laterals



Broad area inspections

Area 1.

Location: Eastern boundary of school

Recommendations:

• Carry out deadwood removal

Area Photo



Area 2.

Location: Nature Play area

Recommendations:

- Carry out deadwood removal
- Crown lift pruning
- Load reduction pruning to over-extended lateral branches

Area Photo



Site Map



Arborists are tree specialists who use their education, knowledge, training, experience and research to examine individual trees and tree stands. Arborists recommend measures to enhance the structure, health, stability and appearance of trees, while attempting to reduce the risk of living near them. Clients may choose to accept or disregard the recommendations of the arborist. Or seek additional advice.

Arborists cannot detect every condition that could possibly lead to the structural failure of a tree. Trees are living organisms subject to attack by disease, insects, fungi and other forces of nature. There are some inherent risks with trees that cannot be predicted with any degree of certainty, even by a skilled and experienced arborist. Arborists cannot predict acts of nature including, without limitation, storms of sufficient strength, which can cause even a healthy tree to fail. Any entity who develops land and builds structures with a tree in the vicinity should be aware of the risks involved with the development of areas within a trees target zone. Arborists cannot guarantee that a tree will be healthy or safe under all circumstances, or for a specified period of time. Likewise, remedial treatments, like medical care, cannot be guaranteed 100%.

It is strongly recommended that all tree management operations be carried out or supervised by a certified or AQF level 4 arborist or above.

Neither this author nor has King's Tree Care assumed any responsibility for liability associated with this tree stand, the future demise and/or any damage, which may result there from. To live near trees is to accept some degree of risk.

Please feel free to contact me should any further information be required.

Regards,

Ben Jorgensen



(Appendix ORD: 13.1B) 1917. 17 admitted Thomas Smith enrolment #5. 19. 7. 7. 8.17 Arbon Day was celebrated. The morning session devoted to gardening planting of trees. etc. afternon ression the pupils were entertained to afternoon tea. (12 trees (assorted) blated.) 7. 8.17 Lyall Winduss returned. A School. after an absence of one. three maths 24. 8. 17. School closed to day for mia wenter. Vacation Weekly tests arithmetic still shows a beakness in the II + I Spelling much inproved throughout the School. 3. 9. 14 School re opened to day. after this Winter Vocation. #2 Scholars in attendance Ilida Robinson Las left. She is required at home to help. M. 9. 17. Work as usual. Testo show a great improvement n' Spelling and cnithnetic 3rd Sta Still very weak, the two Rossite, boys in Lasticular: particular. 4. 9. 17 Admitted Itella Clarke. Hilda Robissi has lept, her mother requires her al home (14 your age.) 17. 9. 17 admitted mande , Donis Incorrect. brookment. 48.

RISK ASSESSMENT TOOL

OVERALL RISK EVENT:

Request for Spotted Gum at Burekup Primary School (River Valley Primary School) to be placed on the Dardanup Councils Heritage Register

RISK THEME PROFILE:

7 - Environment Management

RISK ASSESSMENT CONTEXT:

Strategic

CONSEQUENCE CATEGORY	RISK EVENT	PRIOR TO TREATMENT OR CONTROL			RISK ACTION PLAN	AFTER TREATEMENT OR CONTROL		
		CONSEQUENCE	LIKELIHOOD	INHERENT RISK RATING	(Treatment or controls proposed)	CONSEQUENCE	LIKELIHOOD	RESIDUAL RISK RATING
HEALTH	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.
FINANCIAL IMPACT	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.
SERVICE INTERRUPTION	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.
LEGAL AND COMPLIANCE	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.
REPUTATIONAL	The tree has a level of significance and if removed from the site could result in community comment	Minor (2)	Unlikely (2)	Low (1 - 4)		Minor (2)	Unlikely (2)	Not required. Low (1 - 4)
ENVIRONMENT	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.
PROPERTY	No risk	Not Required - No Risk Identified	N/A	N/A	N/A	Not required.	Not required.	Not required.

<u>ז</u> > υ



Notice of Motion Local Government Act 1995 [5.25(1)e] Standing Orders Local Law 2014 [4.12]

Date Received: 15-11-23	
Signed by CEO:	

I request that the Chief Executive Officer of the Shire of Dardanup put the following information and motion to the Ordinary Council Meeting to be held:

 For the OCM to be

 held on:
 22/11/2023

Corymbia maculata (Western Spotted Gum)

This tree is located on the grounds of the River valley Primary School and is the responsibility of the Building Management Authority.

The above tree was planted on arbor day 1917. It is an icon of the local community. In recent years there have been concerns over the tree's suitability within the bounds of the the Burekup School. However, over the past 106 years the tree has caused no problems, and in recent years (since the rebuild of the school) the tree is inspected every two years to ensure that its risk profile is compatible with the River Valley School.

Attached is a copy of the 2021 report issued by Ben Jorgensen ISA Certified Arborist AU-0334A, of Kings Tree Care.

The report clearly states that the tree is of minimal risk but does point out there is a possibility of failure, and that the consequences could be severe.

To mitigate such failure, and avoid such consequences, it is recommended that the tree Carry out deadwood removal, minor load reduction pruning to over-extended laterals, carry out aerial inspection of crown during works – report to BMW if required.

The Shire I believe would be fully aware of the risks associated with trees in public places, and because of that awareness, they engage contractors to deal with problematic trees.

Motion: That the above tree be placed on the Dardanup Shires Heritage List.

I recommend, on behalf of the Burekup Community, that the above Western Spotted Gum be placed on the Dardanup Shire Councils Heritage Register.

\\dardanup.wa.gov.au\Profiles\$\RedirectedFolders\cathy\Desktop\OC\Notice of Motion.docx



Notice of Motion

Local Government Act 1995 [5.25(1)e] Standing Orders Local Law 2014 [4.12] Date Received:

Signed by CEO:

Attachments:

Tree Inspection and Recommendations Prepared for: Department of Finance – Building Management & Works River Valley Primary School -Burekup 03/03/2021 Written by: Ben Jorgensen ISA Certified Arborist AU-0334

Signature:

Elected member Name:

Cr Mark R HUTCHINSON

Date:

14/11/2023

\\dardanup.wa.gov.au\Profiles\$\RedirectedFolders\cathy\Desktop\OC\Notice of Motion.docx*

Note: A notice of motion under subclause (1) is to be signed by the member and given to the CEO at least 4 clear working days before the meeting at which the motion is to be moved.