

Infrastructure Directorate

APPENDICES

Item 12.4.1 - 12.4.2

ORDINARY COUNCIL MEETING

To Be Held

Wednesday, 29th of October 2025 Commencing at 5.00pm

Αt

Shire of Dardanup
ADMINISTRATION CENTRE EATON
1 Council Drive - EATON

RISK ASSESSMENT TOOL

OVERALL RISK EVENT: Pratt Road Footbridge – Expressions of Interest

RISK THEME PROFILE:


1 - Asset Sustainability Practices

13 - Project Management

RISK ASSESSMENT CONTEXT: Operational

CONSEQUENCE		PRIOR TO T	REATMENT OR	CONTROL	RISK ACTION PLAN	AFTER TREATEMENT OR CONTROL			
CATEGORY	RISK EVENT	CONSEQUENCE	CONSEQUENCE LIKELIHOOD INHERENT RISK RATING		(Treatment or controls proposed)	CONSEQUENCE	LIKELIHOOD	RESIDUAL RISK RATING	
HEALTH	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
FINANCIAL IMPACT	Current budget allocation is insufficient to complete the project.	Moderate (3)	Likely (4)	High (12 - 19)	Add funds to enable completion of the project.	Insignificant (1)	Possible (3)	Low (1 - 4)	
SERVICE INTERRUPTION	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
LEGAL AND COMPLIANCE	If no action is taken, the footbridge will eventually collapse.	Moderate (3)	Possible (3)	Moderate (5 - 11)	Either renew the footbridge, or close off the bridge to public access and demolish when deemed unsafe.	Insignificant (1)	Rare (1)	Low (1 - 4)	
REPUTATIONAL	If no action is taken, the footbridge will eventually collapse and the Shire will be exposed to community disapproval.	Moderate (3)	Possible (3)	Moderate (5	Either renew the footbridge, or close off the bridge to public access and demolish when deemed unsafe.	Insignificant (1)	Rare (1)	Low (1 - 4)	
ENVIRONMENT	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
PROPERTY	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	






SITE PLAN NOT TO SCALE



AMENDMENT DESCRIPTION	BY	DATE	APPROVED	REVIEWED FOR CONSTRUCTION	N AUTHORISED FOR APPROVAL	L APPROVED FOR CONSTRUCTION	ON DRAWING TITLE					
A PRELIMINARY	B.B.	26.02.2025					WATSON RESERVE - NEW ENTRY		IN	IFRASTRUCTURE		
				DRAWN	DRAWN DATE	TARDIS RECORD NUMBER			111	INASTRUCTURE		
				− B .B.	21.02.2025		PRATT ROAD, EATON				Claire	Davidava
				THIS DRAWING IS AND	SHALL REMAIN THE SC		OLTE DI ANI			DRAWING NO.	-Shire of	L)ardanunl
					ANUP'. THE DRAWING MA		SITE PLAN		20	005 ON / 404 O4		Dai dai lap
					HICH IT WAS COMMISIO				20)25-CIV-121-01	Administration Centre Eaton	Telephone 08 9724 0000
				LENT, SHOWN, COPIEI		•				OUEETNO	P.O Box 7017- 1 Council Drive	Facsimile 08 9724 0091
				WRITTEN AUTHORISA				DATUM.	AHD	SHEET NO. SHEET SIZE	Eaton Western Australia 6232	Online www.dardanup.wa.gov.au
I		I		1				I GRID SYS	TEM GDA94	3 3	ABN: 57 305 829 653	





PART PLAN 1

SCALE; 1:400 at A3 0 4m 8 12 16 20






AMENDMENT DESCRIPTION	BY	DATE	APPROVED	REVIEWED FOR CONSTRUCTION	AUTHORISED FOR APPROVAL	APPROVED FOR CONSTRUCTION	N DRAWING TITLE				
A PRELIMINARY	B.B.	26.02.2025					WATSON RESERVE - NEW ENTRY		NFRASTRUCTURE		
				DRAWN	DRAWN DATE	TARDIS RECORD NUMBER		' I	MINASINOCIONE		
				B.B.	21.02.2025		PRATT ROAD, EATON				
				THE DRAWING IS AND	CHALL DEMAIN THE COLE				DRAWING NO.	TShire of Dardanuble	
				SHALL REMAIN THE SOLE		PART PLAN 1		005 011/404 00			
			'THE SHIRE OF DARDANUP'. THE DRAWING MAY ONLY BE USED FOR THE PURPOSE FOR WHICH IT WAS COMMISIONED, AND MAY NOT BE				2025-CIV-121-02		Administration Centre Eaton Telephone 08 9724 0000		
					O OR OTHERWISE DUPLICA	,				P.O Box 7017- 1 Council Drive Facsimile 08 9724 0091	
				WRITTEN AUTHORISAT		AILD WIIIIOUI IIIL		DATUM. AHD	SHEET NO. SHEET SIZE	Eaton Western Australia 6232 Online www.dardanup.wa.gov.au	
				WITH LIN AUTHORISAT	HON OF THE OWNER.			GRID SYSTEM GDA94	STIEET SIZE	ABN: 57 305 829 653	

www.dardanup.wa.gov.au






PART PLAN 2

SCALE; 1:400 at A3 0 4m 8 12 16 20





	AMENDMENT DESCRIPTION	BY	DATE	APPROVED	REVIEWED FOR CONSTRUC	CTION AUTHORISED FOR APPROVAL	APPROVED FOR CONSTRUCTION	DRAWING TITLE					
Α	PRELIMINARY	B.B.	26.02.2025					WATSON RESERVE - NEW ENTRY	l II	NFRASTRUCTURE	•		
		·			DRAWN	DRAWN DATE	TARDIS RECORD NUMBER	PRATT ROAD, EATON	"	WITHOUT ONL	•		
		·			B.B.	21.02.2025		TRATTROAD, LATON		DRAWING NO.		Chiro of [7
					THIS DRAWING IS A	AND SHALL REMAIN THE SOLE	PROPERTY OF	PART PLAN 2		DRAWING NO.		15hire of L	ノC
		 I				RDANUP'. THE DRAWING MAY			20)25-CIV-121-03			.
						R WHICH IT WAS COMMISIONE	•		_`	220 011 121 00		P.O Box 7017- 1 Council Drive	Telepho Facsimi
		(1		_1	PIED OR OTHERWISE DUPLICA ISATION OF THE OWNER.	ATED WITHOUT THE		DATUM. AHD	SHEET NO.	SHEET SIZE	Eaton Western Australia 6232	Online
		1			WRITTEN AUTHORI	ISATION OF THE OWNER.			GRID SYSTEM GDA94		SHEET SIZE	ABN: 57 305 829 653	



From: Zane Jones <zane@jonesws.com.au> Sent: Wednesday, 8 October 2025 12:27 PM

To: Chantal Shorter < Chantal. Shorter@dardanup.wa.gov.au>

Cc: Daniel Fry <frydaniel7@gmail.com>; Burekup Cricket Cl <burekupcc@gmail.com>

Subject: FW: Signs Burekup Cricket Club

You don't often get email from zane@jonesws.com.au. Learn why this is important

A CAUTION: This email originated from outside the Shire of Dardanup.

Do NOT click links or open attachments unless you recognize the sender and know the content is safe. Do NOT enter any username or passwords and report any suspicious content.

Hello Chantal

Hope you are well.

Introducing myself, Zane Jones. I'm a fellow Burekup Cricket Club member and will be assisting Daniel Fry and the Burekup CC on the additional cricket net project.

I have been advised that there is a site meeting being scheduled for this/next week but in the interim I would like to address the proposed additional cricket net location as per email below, along with further commentary on raised points below.

Early 2025, there was a site meeting with members of the Burekup CC and Nigel Lyon. It was agree by all parties the location of the proposed addition cricket would best suit the North side of the current nets as per indicated on below.

This location was recommended due to the below considering factors,

- Cost of the removal/permits of 2x small trees on the North side of existing nets compared to the cost of the large tree on the South side.
- Removal of 2x North side trees for additional net will ensure a safe setback from other existing tree that could fall and damage the existing/new nets.
- Remove of 2x North side trees for additional net will greatly reduce the safety hazard of honky nuts falling on the bowlers runup causing serious injury due to slipping.
- As the extra net will double as a bowling machine net and requiring power. The additional net location
 on the North side of existing nets will remove the trip hazard of the required extension cord on the
 existing net bowling runup area. If the additional net was to be located on the South side of additional
 net, underground power will need to be installed from the current cricket shed to addition net. This
 would increase the project budget.
- The carpet on the current South side practice net has been stained due to the already overhanging tree on the south side. This carpet will need to be replaced in the near future as the carpet is becoming damaged. Installation of the additional net under this tree would cause the new carpet to meet the same scenario.


The required removal of the 2x trees has already been approved. If the additional net was to be located on the south side of the existing, there will be a large tree that would need to be removed. This would increase tree removal costs and also require the time consuming process of obtaining a permit to remove the tree. There has been comments around the South tree in question being pruned to suit. If this was to be undertaken, we are of the opinion that the tree would be very lopsided increasing falling risk (Professional opinion required) If the tree was to fall, this would cause damage to the addition net, also the preferred setback required to remove the honky nut safety risk on the bowlers runup would not be satisfied.

If available, can I please request concept plan that are drawn to scale with the location of the proposed future carpark that will be effected?

This would assist with physically marking out the proposed car park footprint against the existing nets. The concept plans we currently have available have no scale.

Please let me know if any further info is required.

Thanks for your time Chantel.



Preferred Location of Additional Cricket Net in Yellow




2x Tree Removal Required on North side existing Nets (Preferred Location)



Proposed Relocation Tree Removal Required on South Side of Existing Nets



Proposed Relocation Falling Hazard of Tree on South Side of Existing Nets



Example of Honky Nut Safety Risk on Bowling Runup



Net Carpet Damage Caused by Tree

Regards Zane Jones





Please consider the environment before you print this email



Kaya. We acknowledge that Jones Welding Solutions operates on both Wardandi Noongar Boodja and Kaniyang Noongar Boodja. We acknowledge the Wardandi and Kaniyang people as the Traditional Custodians of the land on which we deliver our services and respect their continuing connection to the land, water and community. We offer our respect to Elders past, present and emerging.

From: Chantal Shorter < Chantal.Shorter@dardanup.wa.gov.au >

Date: Tue, Sep 30, 2025 at 9:21 AM Subject: RE: Signs Burekup Cricket Club To: frydaniel7 <frydaniel7@gmail.com>

Cc: Burekup Cricket Cl < burekupcc@gmail.com >

Hi Daniel,

I appreciate your time on the phone, and for providing me with the additional information.

The Burekup Concept Plans have been endorsed by Council and has also been workshopped with the community and user groups such as the Cricket Club.

The Director of Infrastructure, Theo, conducted a site visit on Friday and has advised that tree removal is not required for the original location as per the Concept Plans. There is adequate space for construction and only minor tree pruning would be required.

The alternative location you are proposing would require the removal of only one tree and would also have significant impact on the future carpark. Carparks must comply with Australian Standards as provided for on the Concept Plans, which means that should the cricket net be constructed on the side you are proposing, the carpark would need to be reduced.

Theo has also advised that the construction of the new changerooms is going ahead, and a provision will be made to ensure there is a GPO located on the exterior of the building which should assist with future power supply.

Can you please advise if the Cricket Club would be willing to reconsider the original location as provided for in the concept plans?

Kind regards,

Chantal Shorter

Building Property Management Officer



A: 1 Council Drive | PO Box 7016 | Eaton WA 6232 T: 08 9724 0341 | E: Chantal.Shorter@dardanup.wa.gov.au

W: www.dardanup.wa.gov.au





From: frydaniel7 < frydaniel7@gmail.com Sent: Friday, 26 September 2025 12:55 PM

To: Chantal Shorter < <u>Chantal Shorter@dardanup.wa.gov.au</u>>

Cc: Burekup Cricket Cl < burekup Cricket Club Subject: Re: Signs Burekup Cricket Club

A CAUTION: This email originated from outside the Shire of Dardanup.

Do NOT click links or open attachments unless you recognize the sender and know the content is safe. Do NOT enter any username or passwords and report any suspicious content.

Hi Chantal,

The third net position was changed as the original postion had one very large mature tree in the building envelope compared to two smaller ones in the proposed postion. It was easier to get approval through the Department of Water and Environment due to less canopy/ folage being removed as well as a cheaper option to remove.

The third net will be utilised as a purpose built bowling machine training use net hence the gate included in the quote.

In order to run the bowling machine we have also moved the net so it is closer to the power source so that players are not tripping over the power lead.

We weren't aware that the concept plans were final with the exact layout or size of parking bays. The proposed location appears to have minimal impact on Concept plan parking and would give more room to place shed away from current caravan parking bays.

Regards Daniel Fry.

On Fri, 26 Sept 2025, 12:16 pm Chantal Shorter, < chantal.Shorter@dardanup.wa.gov.au wrote:

Hi Daniel,

The documents are currently sitting with the CEO for signing.

A question has been raised as to the proposed location of the third cricket net. In accordance with the Burekup Concept Plans (attached), the third cricket net is to be located on the other side.

This would ensure that no trees are required to be removed and would also allow for future works to occur such as additional parking and the relocation of the current shed.

Can you please advise why you have changed the proposed location from what is provided for in the endorsed Concept Plans?

Thank you,

Chantal Shorter

Building Property Management Officer



A: <u>1 Council Drive</u> | PO Box 7016 | Eaton WA 6232 **T:** 08 9724 0341 | **E:** <u>Chantal.Shorter@dardanup.wa.gov.au</u>

W: www.dardanup.wa.gov.au



11



From: Daniel Fry < frydaniel7@gmail.com>
Sent: Thursday, 25 September 2025 3:01 PM

To: Chantal Shorter < Chantal.Shorter@dardanup.wa.gov.au>

Cc: Burekup Cricket Cl < burekupcc@gmail.com >

Subject: Re: Signs Burekup Cricket Club

A CAUTION: This email originated from outside the Shire of Dardanup.

Do NOT click links or open attachments unless you recognize the sender and know the content is safe. Do NOT enter any username or passwords and report any suspicious content.

Hi Chantal,

Thank you for the information below re signage.

If possible can you please update status of Budget money and Building approvals for the proposed third net.

Kind Regards

Daniel Fry.

On Thu, 25 Sept 2025, 2:47 pm Chantal Shorter, < chantal.Shorter@dardanup.wa.gov.au wrote:

Hi Daniel,

Thank you for your email outlining the proposed signage for Burekup Cricket Club.

I have contacted the Burekup District Country Club as the shed is also within their leased area. They have advised that the committee is in agreeance with your proposal.

I have also forwarded the request through to our Planning Department who has advised the below-

The signs would require a DA unless the following exemption criteria are met:
I have also attached the Shire's local Planning Policy for advertising signage that has some additional information that may be useful.
Please don't hesitate to contact me if you have any questions.
Thank you,
Chantal Shorter Building Property Management Officer A: 1 Council Drive PO Box 7016 Eaton WA 6232 T: 08 9724 0341 E: Chantal.Shorter@dardanup.wa.gov.au W: www.dardanup.wa.gov.au
From: frydaniel7 < frydaniel7@gmail.com > Sent: Friday, 19 September 2025 8:04 AM To: Chantal Shorter < Chantal.Shorter@dardanup.wa.gov.au > Subject: Signs Burekup Cricket Club
⚠ CAUTION: This email originated from outside the Shire of Dardanup. Do NOT click links or open attachments unless you recognize the sender and know the content is safe. Do NOT enter any username or passwords and report any suspicious content.
Hi Chantal
As discussed proposed signs to put on exterior of cricket shed
On apex above sliding door
One sign on center net. Both signs made of aluminium composite.
Smaller signs made of conrflute to put up at local shop and school.

_			_	
RР	ϭar	de.	Dan	iel

Sent from my Galaxy

"This message contains privileged and confidential information intended only for the use of the addressee or entity named above. Use of this information beyond this intended use is unauthorised"

"This message contains privileged and confidential information intended only for the use of the addressee or entity named above. Use of this information beyond this intended use is unauthorised"

"This message contains privileged and confidential information intended only for the use of the addressee or entity named above. Use of this information beyond this intended use is unauthorised"

RISK ASSESSMENT TOOL

OVERALL RISK EVENT: Burekup – New Cricket Practice Net Location

RISK THEME PROFILE:

6 - Community Engagement

13 - Project Management

RISK ASSESSMENT CONTEXT: Strategic

CONSEQUENCE	CONSEQUENCE SIGN FUELT		REATMENT OR	CONTROL	RISK ACTION PLAN	AFTER TREATEMENT OR CONTROL			
CATEGORY	RISK EVENT	CONSEQUENCE	LIKELIHOOD	INHERENT RISK RATING	(Treatment or controls proposed)	CONSEQUENCE	LIKELIHOOD	RESIDUAL RISK RATING	
HEALTH	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
FINANCIAL IMPACT	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
SERVICE INTERRUPTION	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
LEGAL AND COMPLIANCE	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
REPUTATIONAL	Council has an endorsed concept plan for Burekup that shows the location for the new practice net.	Minor (2)	Possible (3)	Moderate (5 - 11)	Council to attempt to follow the endorsed concept plan to best represent the community plan.	Insignificant (1)	Rare (1)	Low (1 - 4)	
ENVIRONMENT	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	
PROPERTY	No risk event identified for this category.	Not Required - No Risk Identified	N/A	N/A	Not required.	Not required.	Not required.	Not required.	

(Appendix ORD: 12.4.2C) BUREKUP PROPOSED IMPROVEMENTS: - RANKED IN ORDER AS PER OUTCOMES OF THE DARDANUP COMMUNITY SURVEY MAY 1 - LANDSCAPING ALLOWANCE; \$175,000 2 - SHADE SAIL TO EXISTING PLAYGROUND ESTIMATE; \$26,000 RUSSELL ROAD 3 - SKATE PARK ESTIMATE; \$950,000 GHANGEROOMS AND FUNCTIONS FACILITY

STAGE 1; \$1,620,000 / STAGE 2; \$2,400,000 GARDINER - ACTIVE OPEN SPACE COUNTRY ALLOWANCE; \$140,000 6 - CRICKET OVAL LEVELING AND PITCH UPGRADE FXISTING OUTDOOR EXISTING EXISTING HARDCOURTS AREA **EXISTING** ALLOWANCE; \$140,000 PLAY JTURE MULTI-USE COURTS CARPARK GROUND COUNTRY CLUB ABLUTIONS AND ENTRY UPGRADE ESTIMATE; \$185,000 EXISTING OVERED 8 - AREA LIGHTING ESTIMATE; \$85,000 TELSTRA EXISTING PLAY GROUND (1) EXCHANGE STREET 9 - BOLLARD PROTECTION OF OVAL ESTIMATE; \$15,000 EXISTING O PUMP TRACK
ESTIMATE; \$250,000 PRIMARY SCHOOL - UPGRADE EXISTING HARDCOURTS

ESTIMATE: \$410.000 AREA ESTIMATE; \$410,000 COUNTRY CLUB COVERED AREA UPGRADE ESTIMATE; \$185,000 AMPHITHEATRE TRANSPORTABLE - SHORT STAY RV AREA UPGRADE - ACCESS ROAD, ROUNDABOUT AND PARKING ESTIMATE; \$273,000 - BEAUTIFICATION OF TELSTRA EXCHANGE ALLOWANCE; \$56,000 **EXISTING** PRACTICE NETS 6 - ADDITIONAL CRICKET PRACTICE NET ESTIMATE; \$27,000 - RELOCATE CRICKET SHED ESTIMATE; \$58,000 EXISTING CRICKET NET - RELOCATED OVAL CRICKET ALL PROJECTS IDENTIFIED ABOVE ARE SHED SUBJECT TO EXTERNAL FUNDING FROM STATE AND FEDERAL GOVERNMENT. SHOULD FUNDING NOT BE RECEIVED, THE SHIRE WILL BE UNABLE TO IMPLEMENT STREET CASTIEAU EXISTING THESE PROJECTS. SHORT STAY RV-ARFA FEATURES LEGEND: 13 -- PROPERTY BOUNDARY EXISTING TO BE DEMOLISHED EXISTING GOAL POSTS EXISTING WALLS **NEW WALLS** EXISTING BLUE TREE NEW CONCRETE KERB RELOCATED. TO REMAIN BBQ AREA NEW ASPHALT NEW CONCRETE PATH (GREY) NEW LANDSCAPING GARDINER TREE TO BE REMOVED ACTIVE OPEN SPACE NEW STREET TREE NEW PARK TREE NEW BOLLARDS Not to scale NEW POLE LIGHTING Overall Concept Plan - Burekup

Concept Plan

DESIGNED

DRAWN

BB

DRAWN DATE

24.07.2024

AUTHORISED

NR

DRAWING NO. 2024-CPT-100-01

В

ENDORSED

TN

Shire of Dardanup